

# **APPENDIX B**

## **PHOTOGRAPHS OF THE STANDARD MINE SITE**

## Photo legend and descriptions

---

### Page 1

Top: View to the north of Standard Mine. The tailings pond is in the foreground and the remaining mine structures are in the background.

Bottom: View to the southwest of the tailings pond. Note the breach in the tailings dam.

### Page 2

Top: Breach in the tailings dam.

Bottom: View to the north of existing mine buildings. Ore cart rail and associated structures are prominent.

### Page 3

Top: Remaining concrete pad and foundation for mine buildings south of rail structures.

Bottom: Surface drainage from mine area, with Elk Creek flowing along bank in background of the picture.

### Page 4

Top: Surface drainage into tailings pond and Elk Creek.

Bottom: View to the south of remaining buildings behind rail structures.

### Page 5

Top: Main adit, or tunnel, for mine.

Bottom: View to the north of surface drainage from main adit and abandoned mine buildings.









